VOLVO

Volvo Car USA LLC

volvo Car USA LLC	lechnicai Journai		
Technical Journal Title	Ref. No.		
Front door decor panel, noi	TJ 32037.4.0		
Issuer (Dept.)		Issue Date	Status Date
Technical Service	6/19/23	6/30/23	
Car Market	Partner	Function Group	
United States and Canada	3 US 7510 Volvo Car USA	8316	
Function Description		Page	_
COMP INNER DOOR	Page 1 of 3		

Attachment

File Name	File Size
TJ32037.pdf	0.0752 MB

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*VST Op No changed

Noise from front door Decor panel when playing music or closing door. The noise may be coming from loose washers on the screws, see attachment.

CSC Customer Symptom Codes

Code	Description
F9	Doors/Squeak/rattle/When opening/closing
G8	Doors/Squeak/rattle/Front side door

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2016-2019		0000561-0428750	201505-201828

SERVICE:

Tap on the panel and listen for a rattling noise, if a noise is heard, tighten the screw slow and gently.

VST Operation Number

VST Operation Number	Description
99921-2	General reimbursement
85120-2	Panel side door front remove-install

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8316.

To view TJ attachments continue to next page. This TJ has one attachment.

Page 2 of 3 2023-06-30



TJ32037

2023-06-30 Page 3 of 3