



# Diagnostic Trouble Code (DTC) P113600 NOx Sensor 1/2 Correlation Calibration Error Bank 1 - Model Year 2024



Internal Content

PIL-149047

MY 2024

P113600 is a newly introduced fault code for OBD2023 emissions to meet California Air Resources Board (CARB) NOx gap requirements. Vehicles built with OBD2023 emissions may experience occurrences of P1136 when there is no issue present.

### If a vehicle has P1136 present:

1. Check the Engine ECU (EMS) Main Software (MSW) part number.
2. Compare the MSW number to the list below:

Software Part Number
24352217.P01
24529970.P01
24352221.P01
24541476.P01

3. If the MSW number matches one of the listed part numbers, clear faults and release the vehicle.

This is a software issue that will be resolved in a future release. This solution will be updated when more information is available.





Tags

[p113600](#)

[p1136-00](#)

[mack](#)

[volvo](#)

Categories

Make and Model > Mack > CXU/CHU/PI - Pinnacle

Make and Model > Mack > LEU - TerraPro Low Entry

Make and Model > Mack > LR

Make and Model > Mack > TD - Titan

Make and Model > Volvo > VNL

Make and Model > Volvo > VNR

Make and Model > Volvo > VNM

Make and Model > Volvo > VNX

Make and Model > Volvo > VAH

Make and Model > Volvo > VHD

Make and Model > Mack > MRU/TE - TerraPro

Vehicle System > Control Systems

Make and Model > Mack > AN - Anthem

Make and Model > Mack > GU/GR - Granite

**Related links and attachments**

No links or attachments available



**Feedback**

[Give feedback](#)

to help improve the content of this article