Reference	SSM76013
Models	New Range Rover / L460 New Range Rover Sport / L461
Title	Panoramic Roof Opening Panel And/ Or Roof Blind One Touch Inoperative At PDI
Category	Body
Last modified	08-Jun-2023 00:00:00
Symptom	105000 Roof Options
Content	Issue: Jaguar Land Rover have recently received a number of warranty claim submissions for reset of the panoramic roof opening panel and/ or panoramic roof blind (where fitted) to enable one touch

Issue: Jaguar Land Rover have recently received a number of warranty claim submissions for reset of the panoramic roof opening panel and/ or panoramic roof blind (where fitted) to enable one touch operation at Pre Delivery Inspection

Cause: The PDI did not make reference to the requirement to check the one touch operation of the panoramic roof opening panel/ blind and reset where necessary.

Action: The PDI manual vehicle interior section at step 16 has been updated and published in the TOPIx Workshop Manual on the 31/5/23, to check the operation of the one touch panoramic roof opening panel/blind feature and follow the reset procedure where necessary during the PDI.

Note: Please do not submit a warranty claim for reset as the procedure is included in the PDI allowance and the claim may be rejected.

anBhdHRlcnM7MjAyMy0wNy0xMFQxODoyMDozMy41MTdaOzEzNi4yMjYuNDguODU7