

Subject: Engineering Information (EI) - Engine Oil Leaking from Oil Pan

This EI has been revised to end the need for gathering information from the field. Please discard PIE0716.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2022	2022	—	—	2.0L Turbo (RPO LSY)	—
Cadillac	CT4						
	CT5						
	XT4						
	XT5						
	XT6						
Chevrolet	Blazer						
GMC	Acadia						

If you encounter a vehicle with the above condition, refer to *Oil Pan Replacement* in SI.

Version	2
Modified	Released August 23, 2022 Revised June 30, 2023 – Ended the need for gathering further information from the field.