

## **Service Bulletin**

Bulletin No.: 23-NA-120

Date: July, 2023

## **TECHNICAL**

Subject: Information on Lower Steering Wheel Controls Inoperative, DTC B1A37

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	LYRIQ	2023	2024	-	-	All	All

Involved Region or Country	North America				
Condition	Some customers may comment on the lower steering wheel controls not functioning. There may be haptic "click" but the function is not available.				
Condition	During diagnosis a technician may find DTC B1A37 (A failure in a steering wheel control switch circuit is present).				
Cause	The cause of the condition may be due to the protective film on the steering wheel switches with the vehicle in the "on" position.				
Correction	To prevent the issue, remove protective film on switches during PDI while the vehicle asleep. To correct the issue, allow the vehicle to go through a sleep cycle of at least minutes and then try to operate the switches again.				

## **Service Procedure**

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

## **Parts Information**

No parts are required for this repair.

Version	1
Modified	Released July 11, 2023

