

Subject: Engineering Information - Emblem and/or Nameplates on the Liftgate License Plate Applique are Peeling, Bubbling and/or Delaminating

This PI has been revised to end the need for gathering information from the field. Please discard PIE0743.

| Brand: | Model: | Model Year: | | VIN Breakpoint: | | Engine: | Transmission: |
|-----------|--------------|-------------|------|-----------------|----|---------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Suburban | 2023 | 2023 | — | — | — | — |
| | Tahoe | | | | | | |
| GMC | Yukon Models | | | | | | |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

| | |
|-----------------|---|
| Version | 2 |
| Modified | Released April 06, 2023 Revised July 19, 2023 - Ended the need for gathering further information from the field. |