

## ENGINE PRIMARY BELT SHREDDING - P6-3.0L(MHEV)

### Customer Voice:

- Battery light is on

### Technical Description:

- Investigations are ongoing, supported by reviews of returned parts by retailers.

### Status:

- Pulleys and brackets are to be inspected for signs of damage or alignment issues.
- If you encounter this issue:
  - Take pictures of any damaged components
  - Document the condition of all pulleys; BiSG, Idler, Crank, and A/C
  - Please raise a TA to manage the return of components to support the investigation

Refer to SSM 75953 / SSM 75954

### Range Rover

- 19-24MY Range Rover
- 19-24MY Range Rover Sport
- 19-24MY Velar

### Defender

- 20-23MY Defender

### Discovery

- 19-24MY Discovery

### Jaguar

- 19-24MY F-PACE
- 19-21MY XE

