

SQUEAK/RATTLE TYPE SOUND FROM WARNING TRIANGLE LOCATION IN LOADSPACE AREA

Customer Voice:

- That there is a squeak or rattle in the rear loadspace area of the vehicle.

Technical Description:

- The roadside warning triangle kit may be moving around in the mounting tabs.

Status:

- To address this concern, a Velcro strip has been added to prevent the triangle kit movement in production from PA107083.
- **SSM 75858** has been published to provide repair guidance by adding a Velcro strip that is locally sourced.

Range Rover

- 23MY RR Sport

