



Service Bulletin


Bulletin No.: 23-NA-130

Date: July, 2023

TECHNICAL

Subject: Driver Side Mirror Distorted

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer	2019	2023				

Involved Region or Country	North America
Additional Options (RPOs)	
Condition	<p>Some customers may comment on the driver side view mirror being distorted with squiggly lines going through it.</p> 
Cause	The cause of the condition may be too much current going to the mirror defogger circuit.

6388604

Correction	Before replacing the mirror, check connector X500 for corrosion. If corrosion is found, then repair as needed prior to replacing the mirror. Identify water intrusion pathway and repair to prevent future water intrusion into connector. Refer to <i>Repairing Connector Terminals in SI</i> .
------------	--

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
54308560	Connector Kit Replacement	Use Published Labor Operation Time

Version	1
Modified	Released July 24, 2023

