
Reference	SSM76031
Models	F-PACE / X761
Title	X761 23MY roof opening and blind panel incorrect operation.
Category	Body
Last modified	10-Jul-2023 00:00:00
Symptom	105000 Roof Options

Content **Issue:**
Roof opening panel blind will not automatically open when the roof opening panel is requested to be tilted or opened.

Cause:
Incorrect software installed in the roof opening blind motors.

Action:
Replace both roof opening panel blind motors following TOPIx:501-17 - Roof opening panel - roof opening panel blind motor. Service part number **T4A44682 X 2**.

anBhdHRicnM7MjAyMy0wOC0wMlQxMjpyODoyNj44NzNaOzEzNj4yMjYyNTAuMTEzOw==