



Tips and Tricks Revision 9

Date: July 25, 2023
To: Dealer Principal, General Manager, Service Manager, North American Dealer Network
From: Richard Kenton, Technical Director
Dan Schwartz, Service Area Manager

Dear Dealers,

This bulletin is to notify you of important updates included with the recent release of Tips and Tricks Revision 9. A brief summary of each new addition is listed below, but please review the complete document hosted on DCS for further details. [Ducati - Bulletins](#)

Revision 9 New Additions		
#	Subject	Model Affected
1	Indication on new front fork leg seals	MULTISTRADA
2	Hand-Free fuel tank filler plug improvements	MULTISTRADA
3	Error P085F - DQS [Plausibility] - Switch has been pressed for too long	MULTISTRADA
4	Possible presence of creases on the rider seat cover	DIAVEL
5	Instructions on how to remove the timing layshaft seal	ALL MODELS
6	Possible poor sealing of the water pump gear oil seal	ALL MODELS

This bulletin is only applicable for Ducati Motorcycles manufactured and configured for the Ducati North American market (USA, Canada and MX).

For questions about this Service Bulletin,
please contact your Service Area Manager.