

07/21/2023

Team Tip: Heated and Cooled Slingshot Seats



Click here to view Team Tip T-23-06-01 (<https://www.polarisdealers.com/VirtualMaster/StopSiteFiles/TeamTips/SLG/T-23-06-01.pdf>).

Certain LED light fault patterns on the seat control buttons can result from an issue within the seat. Additionally, recent claims have resulted from a poor connection in the seat bottom. Diagnostic and repair information for the heated and cooled seats has been added to the service manual.

View Team Tip T-23-06-01 (<https://www.polarisdealers.com/VirtualMaster/StopSiteFiles/TeamTips/SLG/T-23-06-01.pdf>) for detailed information on troubleshooting and resolution.

Affected Models

Model Year	Models
2022+	All Slingshot Models

Related Articles

Team Tips (<https://ask.polarisdealers.com/Home/ViewArticle?articleNumber=KA-02984>)

Unless noted, trademarks are the property of Polaris Industries Inc.

© 2023 Polaris Industries Inc.

To suggest updates to the article, use the feedback form below. If you are having a technical problem or need assistance, please create the appropriate Ask Polaris Case.

Was this article helpful?

- Yes, it answers my question
- No, it is missing information or visuals
- No, the instructions are unclear
- No, What are the next steps?
- No, I am experiencing a technical error
- Other

How can we improve this article? We would love to hear your suggestions.

Tell us what you would like to see in this article

Send