



15-23-01 - Head Gasket Leakage

Release date: 8/17/2023

Condition

| Applicable Vehicles | | | | | |
|---------------------|-------------|----------------|-------------|------------------|-----------------------------|
| Model(s) | Year | Eng. Code | Trans. Code | Engine Code From | Engine Code To |
| Taos | 2022 - 2023 | 1.5T (DNKA) | All | - | Engine Code DNKA 234 458 |
| Jetta | 2022 - 2023 | 1.5T (DNKA) | All | - | Engine Code DNKA 234 458 |

| Revision Table | | | |
|-----------------|----------------|----------------|-----------------------|
| Instance Number | Published Date | Version Number | Reason For Update |
| 2071245/1 | 08/17/2023 | 15-23-01 | Original publication. |

Customer states coolant level low/leaking from engine area.

Technical Background

Original engine production head gasket design can lead to coolant leaks.

Production Solution

Improve head gasket design and coating as of Engine Number DNKA 234 458 July 27th 2023



Note:

This Technical Bulletin only covers cylinder head gasket replacement for the leaks described within. All other coolant leaks do not apply and will not be covered by this Technical Bulletin.

Service

If a coolant leak is found between the cylinder head and engine block, at the back of the engine below the turbo as indicated in Figure 1. and Figure 2., the head gasket must be replaced per Elsa Pro instructions.



15-23-01 - Head Gasket Leakage

Release date: 8/17/2023



Figure 1.



Figure 2.

Warranty

Information only.



15-23-01 - Head Gasket Leakage

Release date: 8/17/2023

Required Parts and Tools

Always refer to ETKA for the latest part information.

Please review cylinder head gasket replacement in Elsa for single use parts.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.