

WMD4 Workshop campaign - Replacing manual transmission

WMD4 Workshop campaign - Replacing manual transmission

ID Number	WMD4
Models	911 Carrera / Carrera S (997)
Model Years	2005 - 2008
VIN List	Attached
Number of VINs affected	3
Issue Description	<p>A manual transmission, in which an oil baffle plate was not fitted inside the gearbox due to an assembly error, was installed while replacing the transmission on the affected vehicles.</p> <p>If the oil baffle plate is missing, there may not be enough lubrication and as a result, there may be increased wear on the transmission components over the service life of the vehicle.</p> <p>To prevent this from happening, the manual transmission must be replaced.</p>
What should Dealers do?	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>The remedy is now available as of 8/2/23.</p> <p>If a transmission needs to be replaced, your dealer must submit a PRMS Parts Ticket for release. The PRMS Ticket must show photo documentation of the markings on the transmission.</p> <p>All other parts can be ordered via PPL as normal.</p>
TI Number	No. 69-21
Customer Notification	To be posted at a later date.

Attachments

1. [VIN_List_Report_WMD4_2023-08-02.xlsx](#)