



Technical Service Bulletin

SUBJECT:			No: TSB-23-52-001
FRONT DOOR FINISHER ASSEMBLY SCREW TORQUE – SERVICE MANUAL REVISION			DATE: September 2023
			MODEL: See below
CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY PROCESSOR	<input type="checkbox"/> SALES MANAGER

PURPOSE

This TSB provides screw torque information for the Front Door Finisher Assembly in the applicable Service Manual section:

AFFECTED VEHICLES

2022-2024 Outlander

2023-2024 Outlander Plug-in Hybrid

AFFECTED SERVICE MANUAL

- 2022-2024 Outlander Service Manual
- 2023-2024 Outlander Plug-in Hybrid Service Manual

PROCEDURE

Please use the following chart as a guide to add the following page into the affected Service Manual, Group 52, Interior, Trims, Door Trim, Removal and Installation .

Applicable Manual	Pub.No.	Applicable Title
2022 OUTLANDER Service Manual	MSCD-030B-2022 (Volume 1)	INTERIOR └ TRIMS └ DOOR TRIM └ REMOVAL AND INSTALLATION
2023 OUTLANDER Service Manual	MSCD-030B-2023 (Volume 3)	BODY INTERIOR └ INTERIOR └ REMOVAL AND INSTALLATION └ DOOR FINISHER └ Removal and Installation
2024 OUTLANDER Service Manual	MSCD-030B-2024 (Volume 3)	
2023 OUTLANDER (PHEV) Service Manual	MSCD-027B-2023 (Volume 3)	BODY INTERIOR └ INTERIOR └ REMOVAL AND INSTALLATION └ DOOR TRIM └ Removal and Installation
2024 OUTLANDER (PHEV) Service Manual	MSCD-027B-2024 (Volume 3)	



Copyright 2023, Mitsubishi Motors North America, Inc.

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website (www.mitsubishitechinfo.com).

