



Tips and Tricks Revision 13

Date: September 28, 2023
To: Dealer Principal, General Manager, Service Manager, North American Dealer Network
From: Richard Kenton, Technical Director
Dan Schwartz, Service Area Manager

Dear Dealers,

This bulletin is to notify you of important updates included with the recent release of Tips and Tricks Revision 13. A brief summary of each new addition is listed below, but please review the complete document hosted on DCS for further details. [Ducati - Bulletins](#)

Revision 13 New Additions		
#	Subject	Model Affected
1	Possible incorrect evaluation of the wear condition of front wheel bearings	MULTISTRADA
2	Error C1134 – High DRL temperature (update)	MULTISTRADA
3	Melting of coolant distributor due to engine overheating	ALL MODELS

This bulletin is only applicable for Ducati Motorcycles manufactured and configured for the Ducati North American market (USA, Canada and MX).

For questions about this Service Bulletin,
please contact your Service Area Manager.