

SSM 51950

2021-2023 F-150 - 3.5L PowerBoost - Illuminated Powertrain Malfunction (Wrench) Lamp With DTC P084B In The PCM

Some 2021-2023 F-150 vehicles equipped with a 3.5L PowerBoost engine may exhibit an illuminated powertrain malfunction (wrench) lamp with diagnostic trouble code (DTC) P084B stored in the powertrain control module (PCM). Workshop Manual (WSM), Section 307-01B Automatic Transmission - 10-Speed Automatic Transmission – 10R80 MHT, Diagnosis and Testing, DTC Chart and Pinpoint Tests - 3.5L V6 PowerBoost (CN), Pinpoint Test K has recently been updated to provide new direction for DTC P084B. Refer to the WSM, Section 307-01B Automatic Transmission - 10-Speed Automatic Transmission – 10R80 MHT, Diagnosis and Testing, DTC Chart and Pinpoint Tests - 3.5L V6 PowerBoost (CN), Pinpoint Test K for applicable diagnosis.