

UPDATE PRIOR SALE H446 – I-PACE ELECTRIC DRIVE COOLER ISOLATION VALVE

UPDATE PRIOR TO SALE H446 – ELECTRIC DRIVE COOLER ISOLATION VALVE	
AFFECTED MODELS	24MY I-PACE
VOLUME AFFECTED	US 8 CAN 13
REPAIR	A concern has been identified on certain 2024 model year I-PACE vehicles where it may have been installed with an electric drive cooler isolation valve which may not operate as expected. Affected vehicles initially require a valve date code inspection. Vehicles that pass may be released for sale. Failures require the vehicle to continue to be held pending supply of replacement parts.
REPAIR TIME	Inspection: 0.3 hrs + DIDO Repair: 2.5 hrs + DIDO
CAMPAIGN LAUNCH	Inspection bulletin launched: August 17th, 2023 Repair bulletin issued on September 11th, 2023
Notes	Please ensure to inspect all vehicles prior to dispatch. Any failed inspection must be held and cannot be delivered until repair has been completed. To date, 9 vehicles have completed inspections with zero failures.