

**Audi On-car analysis list from October, 1 2023**

**Please contact Audi Helpline before attempting repair**

**All topics have associated worksheets to be filled out and attached to the TAC ticket. Worksheets can be found at: ServiceNet>>Technician References>>Vin-4-Pin>>Worksheets**

	Models	MY	Engine	Trans	Topic	Topic details
PT	Q3	2020-2021	All	All	Coolant warning Lamp	Customer states they receive a low coolant warning in the cluster. Coolant level appears to be full in the reservoir <ul style="list-style-type: none"> <li>Case does not relate to TSB 2061918</li> <li>Photo showing reservoir level</li> </ul>
	A6, A7, Q7, Q8, S4, S5	2019-2023	3.0L	All	Catalytic Converter Inspection , P042000: Catalyst System,Bank1 Efficiency Below	<ul style="list-style-type: none"> <li>GFF Log with all fault codes and completed test plans.</li> <li>Oil and Fuel samples (Hazmat containers can be requested through TAC). After oil sample have been collected, oil and filter should be changed.</li> <li>VIN-4-Pin Worksheet with answers to questions</li> </ul>
	All models with 3.0L engine (EA839)	2021-2023	3.0L (EA839)	All	Abnormal/no sound from engine sound generator	<ul style="list-style-type: none"> <li>Video/ sound recording of abnormal noise/ customer complaint from inside the vehicle before repair.</li> <li>Video/ sound recording while running sound actuator test</li> <li>Upload GFF log with executed test and relevant DTCs to GFF paperless</li> <li>Video/ sound record of noise from inside the vehicle after repair.</li> </ul>
	A4	2023	All	All	Coolant leak from expansion tank	Photo documentation of the source of the leak
	Q3	2019-2023	All	All	P008700 Low fuel pressure	Applies to Q3 models within NVLW only <ul style="list-style-type: none"> <li>DTC P008700</li> <li>Attach completed worksheet on initial TAC contact.</li> </ul>
	A6, A7, Q7, Q8, S4, S5	2020-2024	EA839 3.0L 2.9L	All	Parts Block Belt tension damper 06M903133AA	Only applicable if no prior repairs to Starter generator/ belt drive system performed. See worksheet
	Q4 e-tron	2022-2024	All	All	Charging cable cannot be removed from the vehicle	See e-tron charging questionnaire worksheet
	e-tron Q and SB Q8 e-tron and SB	2019-2024	All	All	Vehicle cannot be charged, charge socket lock without function	See e-tron charging questionnaire worksheet
	Q3	2020-2023	All	All	Q3 oil pan leak	Oil leak found coming from the oil pan.
EL	e-tron GT	2022-2024	All	All	Corrosion found in door module	Customer concern that a door module function is inoperative Upon inspection corrosion is found on door module pins Photo document findings, water test, inspect door harness and pillar connection
	SQ5	2018-2024	All	All	Wire broke at air compressor V66	DTC P089200 Broken/Damaged/Loose connection found at V66 (Suspension Compressor) T3DL
BD	e-tron Quattro e-tron SB	2021-2022	Any	Any	Noise from Front Door Trim Panel	Noise from front door trim panel while driving <ul style="list-style-type: none"> <li>Video of noise before repair is performed</li> <li>Photos of repair</li> </ul>
	A5	2021-2022	Any	Any	Noise from Front Door speaker Grill	Noise from front door trim panel while driving <ul style="list-style-type: none"> <li>Video of noise before repair is performed</li> <li>Photos of repair</li> </ul>