# Service Alert

## Mazda North American Operations Irvine, CA 92618-2922



Subject:

INDENTATION ON REAR OF FRONT SEAT

Service Alert No.: SA-072/23

Last Issued: 10/26/2023

### **BULLETIN NOTES**

## APPLICABLE MODEL(S)/VINS

2022-2023 MX-30

#### **DESCRIPTION**

Some customers may report a dent at the side or rear of the front seat. This is caused by the seat belt buckle resting against the seat.



#### REPAIR PROCEDURE

**Do not replace any parts**, this is a normal condition if the customer allows the seat belt to rest against the seat when retracted. If the buckle is moved away from the seat, the dent will go away after a day or two in the sun. The image below

Page 1 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-072/23 Last Issued : 10/26/2023

is the the same vehicle seen above after one (1) day parked in the sun.



Page 2 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.