

Forward Looking Radar Shortage Fullfilment

Service Category Service Department

Section 366

Technician Skill Level C

Market US, Canada

Applicability

VOLVO

Years	Models
2022 - 2023	VAH, VHD, VN,

Introduction

This Service Campaign is the solution for the Ship Shortage of **Proprietary Hubcap Recall SC0425** that effected **Volvo VAH, VHD, VN, VNE** Models. This Service Campaign also covers trucks that were shipped short from the factory or removed in the field. Volvo Trucks now has a solution to replace the Proprietary Hubcaps with new updated hubcaps.

Production Change Information

This bulletin applies to vehicles built within the specified production changes below.

Brand	Engine	Emission Level	Starting Build Date	Ending Build Date
Volvo	CU15, D11, D13, UE	USA17-24, ZE	08- September-2020	14-January-2022

Warranty Information

This repair is covered by an authorized Service Program. Reimbursement is obtained through the normal claim handling process.			B
Main Labor Code	Description	Hours	
7718-03-02-01	Hub Cap Wheel Cover, Replacement Per wheel	0.1	
Causal Part	23768767 / 23768768		
SCC Authorization Code	S7639		
Expiration Date	August 15, 2024		

Volvo Proprietary Fixed Axle Hubcap Replacement

Parts Information

*Verify parts and quantity needed in IMPACT per VIN

Note* Hub caps are sold as a pair of two.

Part Numbers	Part Names	Quantity
24154267	HUB CAP, KIT, DRIVE, VOLVO, BLACK	*
24154265	HUB CAP, KIT, DRIVE, VOLVO, CHROME	*

Required Tools & Equipment

- N/A

Calibration Information

- N/A

Repair Procedure

1. Secure truck for service.
2. Install all new proprietary hubcap wheel covers.
3. Ensure new hubcaps are fully seated on the wheel.
4. Release the truck to service.

Volvo Proprietary Hubcap wheel cover shown below

