

DEPLOYABLE SIDE STEPS NOISY OR ERRATIC OPERATION

Customer Voice:

- The deployable side steps are noisy in operation or have erratic intermittent operation.

Technical Description:

- The Running Board Control Module (RBCM) may have one of the following DTCs stored: C1002-77, C1003-77, C1004-77, C1005-77, C1008-3A, C1009-3A

Status:

- This may be caused by incorrect installation of the deployable running boards, either loose fixings or incorrect alignment.
- **SSM 76011** has been published to provide diagnostic guidance to repair the concern.
- Hardware should not be replaced unless specifically instructed following the diagnostic procedures.

Range Rover

- 22–24MY Range Rover (L460)
- 23–24MY Sport

