

HEADLAMP CONDENSATION DIAGNOSIS

Customer Voice:

- There is moisture inside the headlamp lens.

Technical Description:

- Headlamps have been replaced for slight condensation concerns that would clear following the Diagnosis and Testing procedures in the Workshop Manual.

Status:

- Engineering have inspected parts returned for investigation and found the Workshop Manual procedures have not been followed.
- For diagnosing headlamp moisture concerns, please refer to **Workshop Manual section 417-01: Exterior Lighting > Diagnosis and Testing > Headlamps > Front and Rear Lamp Condensation**

Range Rover

- 17-24MY Range Rover
- 17 – 24MY Sport
- 17 – 24MY Evoque
- 18-24MY Velar

Defender

- 20–24MY Defender

Discovery

- 17-23MY Discovery
- 15-23MY Discovery Sport

Jaguar

- 19-23MY I-PACE
- 17-23MY F-PACE
- 17-23MY XF
- 19-23MY E-PACE

