

REFERENCE:	Nova Bus Manuals
SECTION:	02: Doors
RS N°:	MQR 7621-NA
EFFECTIVE IN PROD.:	NA

APPLICATION DEADLINES: 2024DE01
CLAIM REFERENCE NUMBER: WB5514

SUBJECT:	Doors
JUSTIFICATION:	Upper door shaft nut may get loose.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
		LABOUR	MATERIAL	
1	Inspect for the presence of the nut and Nord-Lock washers. If required, torque the nut to spec.	Nova Bus	Nova Bus	10 min
2	Install any missing parts if required.	Nova Bus	Client*	5 min

* The cost of the material will be reimbursed when claiming for this service document.

MATERIAL REQUIRED PER VEHICLE

QTY	PART N°	REV.	DESCRIPTION
LEVEL 1			
-	-	-	-
LEVEL 2 (only if required**)			
-	-	-	-

**The material identified in Level 2 is to be ordered only for vehicles that meet the criteria defined in Level 1.

DISPOSAL OF PARTS

REMOVED PARTS ARE:	DISCARDED *	RETAINED	* Dispose of the unused parts and the defective parts in accordance with local environmental standards in effect.
	Yes	-	

REVISION HISTORY

REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY
NR	2023NO21	Initial release	André Pelletier

APPROVED BY:

NQF772004 VERSION 3

Signature
numérique
Irina
Date :
10:44:03 -05'00'

Irina

Negoescu

CLIENT	ORDER	ROAD NUMBER		VIN (2NVY/4RKY...)		QTY
		FROM	TO	FROM	TO	
New York City Transit - NYCT - New York	LD06	8755	8758	L82J3L97 [REDACTED]	L82J3L97 [REDACTED]	4
New York City Transit - NYCT - New York	LD08	8759	8963	L82J5M97 [REDACTED]	L82J8N97 [REDACTED]	205