

 <b>Tesla, Inc.</b> Service Bulletin		<h2>Replace Steering Wheel Due to Material Separation</h2>	
<b>SB-23-32-003</b> October 11, 2023			
<b>Classification</b>		<b>Section/Group</b>	<b>Mobile Service</b>
Repair Bulletin		32 - Steering	Can Perform (where permitted)
<b>Model Year</b>	<b>Model</b>	<b>Country/Region</b>	<b>Build Location</b>
2020 - 2023	Model 3, Model Y	All	Fremont
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Repair Bulletin: This repair bulletin provides instructions on addressing a possible customer concern regarding the operation of Tesla vehicles. These instructions should only be performed by trained professionals.

### Condition

On some Model 3 and Model Y vehicles, the steering wheel cover material may separate from the steering wheel at the 3 o'clock and 9 o'clock position (Figures 1 and 2).

**NOTE:** The material separation of the steering wheel cover is cosmetic only and does not affect the performance or function of the steering wheel.



Figure 1



Figure 2

### Correction

Inspect the vehicle for symptoms related to the condition. If symptoms are present, replace the steering wheel.

Correction Description	Correction	Time	
		Model 3	Model Y
SB-23-32-003 Not Applicable	S012332003	0.00	0.00
Replace Steering Wheel Due To Material Separation	S022332003	0.24	0.18

	Part Number	Description	Quantity
<b>Parts Required</b>	1490214-00-B	STEERING WHEEL - PUR LEATHER	1
	1036655-00-A	BOLT RC M16X1.5X26 PC88 PTP	1
<small>These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the <a href="#">Parts Catalog</a>.</small>			
<b>Special Tools</b>	1143985-00-A	VALVE CORE REMOVAL TOOL	

## Procedure

Replace the steering wheel (refer to Service Manual procedure 32051802; [Model 3](#), [Model Y](#)).

