



## **SSM 52088 2022-2023 F-150 Lightning - Equipped With Front Park Aid (Minor Feature Code HNLAB) - Inoperative Front Parking Sensors With Front Parking Sensors Not Available Sensors Blocked See Manual Message In The Instrument Panel Cluster (IPC)**

Some 2022-2023 F-150 Lightning vehicles equipped with front park aid (minor feature code HNLAB) may exhibit an inoperative front park aid feature with a Front Parking Sensors Not Available Sensors Blocked See Manual message in the IPC without any diagnostic trouble codes (DTCs) associated with the condition. To confirm a vehicle is built with a certain minor feature code, review the build information by double-clicking the vehicle identification number (VIN) in the upper left corner in the Professional Technician System (PTS). This may be due to the software level of the image processing module A (IPMA). This condition does not affect vehicle durability and no additional diagnosis or service is required for this condition at this time. Engineering is working on a solution that is expected in Q1 2024. Monitor OASIS for additional information and schedule service appointments once the repair becomes available.