



# Service Bulletin

File in Section: -

Bulletin No.: PIT5219

Date: August, 2013

## PRELIMINARY INFORMATION

**Subject:** DTC B2600 and B2605 Set With No Other Symptoms

**Models:** 2014 GMC Sierra 1500

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Some technicians may find DTCs B2600.04 and B2605.04 set in the BCM with no other symptoms. These two DTC's may falsely set if the DRL's are operated and the fog lamps are turned on. The lamps will work as designed, and there will be no issues or customer complaints with the lamps.

### Recommendation/Instructions

Engineering is aware of this issue and a fix should be available shortly. In the meantime, if no other symptoms are noted with the DRL operation, these DTC's should be ignored.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.