

Service Bulletin

Bulletin No.: 23-NA-203

Date: November, 2023

INFORMATION

Subject: Information on DTC U1122 - Lost Communication with Electric Park Brake Switch

Stored in History

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|------------|----------|-------------|------|------|----|-----------|---------------|
| | | from | to | from | to | Eligilie. | mansinission. |
| Brightdrop | Zevo 600 | 2023 | 2023 | - | - | All | All |

| Involved Region or Country | North America |
|----------------------------|---------------|

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Important: This technical service bulletin (TSB) can only be completed by BrightDrop dealers or BrightDrop certified repair facilities who have met all BrightDrop specific training, tool and equipment requirements. Repairs must be performed by a technician who has successfully completed the required training. If a vehicle presents itself with the U1122.00 DTC stored in history, Do NOT make any attempts at repair/diagnosis.

Important: Do not replace parts for this condition. U1122.00 is a false setting DTC if stored in history.

| Version | 1 | | |
|----------|----------------------------|--|--|
| Modified | Released November 16, 2023 | | |

