

CLICKING/TICKING NOISE FROM FRONT AXLE WHEN TURNING AT FULL LOCK AT LOW SPEEDS

Customer Voice:

- There is a clicking or ticking type noise from the front axle area of the vehicle while turning either left or right at or near full lock at low speeds.

Technical Description:

- This may be caused by the front wheel bearing/hub assembly not being fully seated.

Status:

- SSM 75779 has been published to provide repair guidance.
- Please ensure the service instructions are followed exactly upon customer complaint.

Defender

- 20 - 23MY Defender

Discovery

- 21 -23MY Discovery

