



Service Bulletin

File in Section: -

Bulletin No.: PIC5257C

Date: July, 2013

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Service Stability Message With Code U0710

Models: 2011 - 2013 Buick Regal
2010 - 2013 Buick LaCrosse
2010 - 2013 Cadillac SRX
2010 - 2013 Chevrolet Camaro, Equinox
2011 - 2013 Chevrolet Cruze
2010 - 2013 GMC Terrain

This PI was superseded to update model years. Please discard PIC5257B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may notice a Service Stability message in the DIC. After further investigation you may find DTC U0710 set by the Steering Angle Sensor.

It should be noted that the Steering Angle Sensor is incorrectly setting this U-code, and it should be setting C0710 code instead.

Recommendation/Instructions

Follow the published diagnostics for DTC C0710 and NOT DTC U0710.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.