



Service Bulletin

File in Section: -

Bulletin No.: PIT5066A

Date: November, 2014

PRELIMINARY INFORMATION

Subject: Intermittent Battery Draw Dead Battery Or HVAC Odor

Models: 2008-2011 Buick Enclave
2009-2011 Chevrolet Traverse
2007-2011 GMC Acadia
2007-2010 Saturn OUTLOOK
2007-2011 Cadillac Escalade Models
2007-2011 Chevrolet Silverado, Avalanche, Suburban, Tahoe
2007-2011 GMC Sierra, Yukon Models

This PI was superseded to update Recommendation/Instructions. Please discard PIT5066.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may report that their vehicle will not crank intermittently due to a dead battery. It has been identified through Engineering that there is a potential for the HVAC afterblow function to cause an intermittent battery draw.

Recommendation/Instructions

If no other vehicle system or component is identified as the root cause for the battery drain condition and the afterblow function is enabled, reprogram the HVAC Control Module with the latest calibration currently available in TIS2WEB.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810015	K33 HVAC System Control Module Reprogramming	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.