



## STAR ONLINE PUBLICATION



**Case Number:** S2308000126

**Release Date:** October 2023

**Symptom/Vehicle Issue:** Check Engine Light (CEL) P257F, P152E, or P0073

**Customer Complaint/Technician Observation:** The customer may complain that their Check Engine Light (CEL) is illuminated. When the technician scans the vehicle, they may find one or more of these DTC's; P257F, P152E or P0073.

**Discussion:** Locate the XY103A connector; in the front left corner under the hood of the vehicle. Disconnect the connector and inspect for any loose pins, repair as necessary. Reconnect the connector ensuring a full connection. Rescan and clear any DTC's. For any DTC's that remain perform published diagnostics in Service Library (SL).

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**




## STAR ONLINE PUBLICATION



CONNECTION:  
XY103A

JEEP WRANGLER (JL)



Dash Harness

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**