

# Technical Service Bulletin

## 91 MIB3: configuration wizard appears without apparent reason

91 23 54 2067843/3 December 11, 2023. Supersedes Technical Service Bulletin Group 91 number 23-95 dated May 9, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, and S5 Sportback	2020 – 2024	All	Not Applicable
A8 e quattro	2021		
A7 e quattro	2021 – 2022		
e-tron quattro, and e-tron Sportback quattro	2021 – 2023		
RS 5, RS 5 Sportback, A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, Q5, Q5 e quattro, Q5 Sportback, SQ5, SQ5 Sportback, Q7, SQ7, Q8, SQ8, and RS Q8	2021 – 2024		
e-tron S	2022 – 2023		
A3, S3, RS 3, e-tron GT, RS e-tron GT, Q3, Q4 e-tron, Q4 e-tron Sportback	2022 – 2024		
Q8 e-tron, Q8 e-tron Sportback, SQ8 e-tron, and SQ8 e-tron Sportback	2024		

## Condition



# Technical Service Bulletin

---

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised header (Added new model years) Revised <i>Service</i> (updated service measure)
2	05/09/2023	Revised header (Added new model years)
1	08/23/2022	Initial publication

## Customer states:

The setup wizard is displayed every time the vehicle is started.

## Technical Background

The setup wizard has not been fully completed therefore it displays on every startup as designed.

## Production Solution

Not applicable.

## Service

**Do not perform any repairs. Any repairs for this concern may be denied.**

Instruct the customer that this condition is normal.

- The customer can either reset the MMI to factory settings and then complete all steps in the setup wizard to fully personalize their vehicle.

**Or**

- The setup wizard can be deactivated via Settings >> Notifications, or via the notification shortcut in the drop-down menu (Figures 1 and 2).



# Technical Service Bulletin



**Figure 1:** Notification shortcut button in the dropdown menu.



# Technical Service Bulletin




Figure 2: Setup wizard deactivation setting.

## Warranty



# Technical Service Bulletin

---

This TSB is informational only and not applicable to any Audi Warranty.

## Additional Information

All part and service references provided in this TSB (**2067843**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.