

# **Technical Service Bulletin**

#### 90 PSS Instrument cluster: Superimposed content in the information display

90 23 62 2072430/1 December 15, 2023.

| Model(s)  | Year | VIN Range | Vehicle-Specific Equipment |
|---|------|-----------|----------------------------|
| e-tron GT, RS e-<br>tron GT, Q8 e-<br>tron, Q8<br>Sportback e-tron,<br>SQ8 e-tron, and<br>SQ8 Sportback<br>e-tron | 2024 | All       | Virtual Cockpit            |

## Condition

#### **Customer States:**

Content is displayed in the information line on top of other content in the Audi virtual cockpit.

#### Workshop findings:

The complaint only occurs in classic performance layout (with power meter in center of display). The concern does not occur in the two other layouts.

In Figure 1, the area affected when the issue is occurs is marked in red.



Figure 1: Superimposed content inside red square.

# **Technical Background**

Software issue in the instrument cluster.

# **Production Solution**

Page 1 of 2

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



# **Technical Service Bulletin**

This bulletin will be updated when more information is available. A solution is currently under development.

### Service

- 1. Explain to the customer that a solution is expected to be available by the end of the 2nd quarter of 2024 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
- 2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

### Warranty

This TSB is informational only and not applicable to any Audi Warranty.

### **Additional Information**

All part and service references provided in this TSB (**2072430**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2023 Audi of America, Inc.

Page 2 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.