



Bulletin No.: PIP5939
Published date: 09/8/2023

Preliminary Information

PIP5939 SES Lamp With DTC P0315

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Corvette Z06	2023	All	All	5.5L LT6	All

Involved Region or Country	North America
Condition	Vehicle may have DTC P0315 setting erroneously with no other drivability symptoms.
Cause	ECM software

Correction:

A software update is currently being developed to address this concern, this pertains to vehicles that have DTC P0315 set with no other drivability or DTC concerns.

Do not replace the ECM for this concern.

At this time it is recommended to perform a CKP sensor/reductor variation learn and release the vehicle

This PI will be updated after the software update has been released.

Version History

Version	1
Modified	09/08/2023 - Created on.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.