



Bulletin No.: PIP5940

Published date: N/A

Preliminary Information

PIP5940 Information on Change of Procedure for Thermostat Replacement on HFV6 Gen2 Transverse Mounted Engines

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	LaCrosse	2017 - 2019	All	All	3.6 LGX	All
Buick	Regal	2018 - 2020	All	All	3.6 LGX	All
Cadillac	XT5	2017 - 2023	All	All	3.6 LGX	All
Cadillac	XT6	2020 - 2023	All	All	3.6 LGX	All
Chevrolet	Blazer	2020 - 2023	All	All	3.6 LGX	All
GMC	Acadia	2017 - 2023	All	All	3.6 LGX	All

Involved Region or Country	North America, Europe, Uzbekistan, Russia, Middle East, Iraq, Israel, Palestine, Argentina, Brazil, Bolivia, Chile, Colombia, Ecuador, Paraguay, Peru, Uruguay, Venezuela, Japan, Cadillac Korea (South Korea), GM Korea Company, China, Taiwan, Thailand, Singapore, Philippines, Australia/New Zealand, Other Africa, South Africa
Condition	The procedure for thermostat replacement has been changed on transverse mounted HFV6 Gen2 engines.
Cause	The procedure was changed to replacement of the thermostat housing only - Not the pipe and water outlet housing.

Correction:

This procedure was changed due to parts being replaced that are not needed and labor time has been changed. The current part 12678779 will no longer be used for thermostat replacement, it will be available for pipe leak replacement only.

Parts Information

Description	Part Number	QTY.
Thermostat Housing	12678780	1

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4032830	Engine Coolant Thermostat Housing Replacement	Use published labor time.

Version History

Version	1
Modified	09/21/2023 - created on.



© 2023 General Motors. All Rights Reserved.