

UPDATE PRIOR SALE N845 – OIL COOLER PIPE JOINT INTEGRITY CONCERN

UPDATE PRIOR TO SALE N845 – OIL COOLER PIPE JOINT INTEGRITY CONCERN	
AFFECTED MODELS	24MY Range Rover equipped with NC11 4.4L V8 engine
VOLUME AFFECTED	US 1520 CAN 219
REPAIR	A concern has been identified on certain vehicles where the fastener used to secure an engine mounted oil cooler hose has been found to be inadequate and hoses are loose post assembly. Vehicles require replacement of two studs with bolts.
REPAIR TIME	Inspection and bolt replacement: 0.3 to 1.6 hrs + DIDO
CAMPAIGN LAUNCH	Inspection and bolt repair instructions were released on Nov 17th, 2023
Notes	Please refer to the warranty portal to identify affected vehicles. Any vehicle that fails the inspection should be repaired using two new bolts. If it is not possible to first remove the studs, the vehicle must continue to be held until the repair bulletin is updated with additional repair instructions. Target date is Dec 6th subject to parts availability.