

# Technical product information

<b>Topic</b>	Infotainment screen turns red sporadically
<b>Market area</b>	Australia E04 Bentley rest Asia and Australia (6E04),China 723 Volkswagen (Anhui) Automotive CO (6723),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
<b>Brand</b>	Bentley
<b>Transaction No.</b>	2055846/9
<b>Level</b>	EH
<b>Status</b>	Approval
<b>Release date</b>	

## New customer code

Object of complaint	Complaint type	Position
information, navigation, communication, entertainment -> radio, navigation, MMI, hard drive device functions	functionality	
information, navigation, communication, entertainment -> instrument cluster, displays, display panels	functionality	

# Vehicle data

## New Continental GT and New Continental GTC

### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
3S3*	2019	E		*	*	*
3S3*	2020	E		*	*	*
3S3*	2021	E		*	*	*
3S3*	2022	E		*	*	*
3S3*	2023	E		*	*	*
3S3*	2024	E		*	*	*
3S4*	2019	E		*	*	*
3S4*	2020	E		*	*	*
3S4*	2021	E		*	*	*
3S4*	2022	E		*	*	*
3S4*	2023	E		*	*	*
3S4*	2024	E		*	*	*

## New Flying Spur

### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
ZG2*	2020	E		*	*	*
ZG2*	2021	E		*	*	*
ZG2*	2022	E		*	*	*
ZG2*	2023	E		*	*	*
ZG2*	2024	E		*	*	*

# Documents

Document name
<a href="#">master.xml</a>

Infotainment screen turns red sporadically

### Customer statement / workshop findings

Infotainment screen 'Goes Red Fully or partially' within the MMI Screen (Figure 1)



Figure 1

### Technical background

#### Revision history 2055846/9

The original questionnaire has now been removed from the TPI

#### **!** NOTICE

Please refer to the Measure section of this TPI

### Production change

Under investigation

### Measure

#### Reset the Infotainment system as follows:

- Press and hold the volume rotary switch (Figure 2) for 10 seconds



Figure 2

#### **!** NOTICE

In the event the issue is resolved the operative must raise a non-technical DISS query stating the issue is now resolved

However

Should the issue still be evident the operative should raise a technical DISS query

### **Warranty accounting instructions**

Warranty type - 110 or 910

Damage Service Number 91 96

Damage Code 00 40

Labour Operation Code 91 96 01 01 (Use 99 index until 08/02/24)

Time 10 TU