



Technical Service Bulletin

90 Audi virtual cockpit: display is blank (DTC B200049 symptom code 10485833)

90 24 76 2068380/3 February 6, 2024. Supersedes Technical Service Bulletin Group 90 number 23-51 dated November 7, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, Q7, SQ7, Q8, SQ8, and RS Q8	2021 – 2024	All	Audi virtual cockpit
A7 e quattro	2021 – 2022		

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Production Solution</i> (added production date) Revised <i>Service</i> (Updated service procedure)
2	11/8/2023	Revised header (Add Model Years, add A6, A7) Revised <i>Service</i> (Updated service procedure)
1	11/7/2022	Initial publication

Customer states:

- The Audi Virtual Cockpit display is blank.

And/or

- Various warning lights are lit on the Audi Virtual Cockpit.

Workshop findings:

The following DTC may be stored in the Instrument Cluster control module -J285- (diag. addr. 0017):

- DTC B200049:** Control module faulty *static/active*, **symptom 10485833**.

Technical Background



Technical Service Bulletin


A hardware issue may cause the Audi Virtual Cockpit to become blank.

Production Solution

Optimized instrument cluster hardware in production as of 08/01/2023.

Service

1. In your warranty claim notes document the production date of the instrument cluster. To do so:
 - a. Using ODIS: Right click diagnostic address 17>>Identification>>Production date:
2. Replace the Audi Virtual Cockpit -J285- according to the instructions of the ELSA repair manual.

 NOTICE
Instrument clusters received with a production BEFORE August 1st 2023 may still be used.

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9025		
Damage Code:	0040		
Labor Operations:	Remove and replace dash panel insert	9025 XXXX	See SRT with associated operations
Diagnostic Time:	GFF	0150 0060	Time stated on the diagnostic protocol (Max 60 TU)



Technical Service Bulletin

	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2068380/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
See ETKA	Instrument Cluster	01

Additional Information

All parts and service references provided in this TSB (**2068380**) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.