



SSM 52240 2023 F-150 Lightning - Diagnostic Trouble Code (DTC) P2DA6 Stored In The SOBDMC - Built On Or After 31-Jul-2023

Some 2023 F-150 Lightning vehicles built on or after 31-Jul-2023 may exhibit DTC P2DA6 stored in the secondary on board diagnostic module C (SOBDMC). If there are no observable symptoms associated with this DTC, this condition does not affect vehicle operation or durability and no additional diagnosis or service is required for this condition. If there is a lack of heat in the vehicle cabin and this DTC is present, refer to the Workshop Manual (WSM), Section 412-00 Climate Control System - General Information, Diagnosis and Testing for diagnosis.