

Technical Service Bulletin



46 TT RS Brake noise

46 13 39 2028811/3 May 24, 2013. Supersedes Technical Service Bulletin Group 46 number 12-25 dated September 26, 2012 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
TT RS	2012-2013	See <i>Service</i> section below	Not applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Service</i> (Add repair instructions)
2	9/26/2012	Revised <i>header data</i> (added model year)
1	2/29/2012	Initial publication

The customer may complain of a high-pitch squeal or squeak from the brake system when the brakes are used at slow speeds. This TSB only applies to vehicles with brake pads and discs that still have significant life left.

Technical Background

Natural frequency of brake components.

Production Solution

Updated front brake pads.

Service

Due to the currently limited supply of parts, this TSB should only be applied the VINs listed below.

1. Confirm that the VIN matches one of the VINs listed below.
2. Replace front brake pads with part number **8J698151L**. Refer to *ElsaWeb* >> *Repair Manual* >> *Chassis* >> *Brake System* >> *46 Mechanical Components* >> *Removal and Installation* >> *Front Brake Pads, TT RS*.

Applicable VINs:

TRUB3AFK0D1900174	TRUB3AFK5D1900431	TRUB3AFK9D1900576
TRUB3AFK4C1900208	TRUB3AFK9C1900284	TRUB3AFK0D1900854
TRUB3AFK8D1900469	TRUB3AFK6C1901568	TRUB3AFK9C1900849
TRUB3AFK2D1900256	TRUB3AFK1D1900264	TRUB3AFK8D1900682
TRUB3AFK7C1900140	TRUB3AFK1D1900975	TRUB3AFK5D1900803
TRUB3AFK7D1900169	TRUB3AFK9D1900853	TRUB3AFK7D1900690
TRUB3AFK7D1900155	TRUB3AFK3D1900816	TRUB3AFK7C1901742
TRUB3AFK6D1900020	TRUB3AFK7D1900270	TRUB3AFKXD1900697
TRUB3AFKXC1901699	TRUB3AFK1D1900717	TRUB3AFK6D1900261
TRUBFAFK1C1014886	TRUB3AFK8D1900004	
TRUB3AFK3D1900525	TRUB3AFK3C1901639	

Technical Service Bulletin



Warranty

Claim Type:	110 - New Vehicle Limited Warranty (NVLW)		
Service Number:	4636		
Damage Code:	0020		
Labor Operations:	Brake pads, front remove+reinstall	4636 2050	50 TU
	Wheels remove+reinstall	4405 2000	20 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2028811/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
8J698151L	Front brake pads	1 set

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.