



Tips and Tricks Revision 2

Date: February 26, 2024
To: Dealer Principal, General Manager, Service Manager, North American Dealer Network
From: Richard Kenton, Technical Director
Dan Schwartz, Service Area Manager

Dear Dealers,

This bulletin is to notify you of important updates included with the recent release of Tips and Tricks Revision 2. A brief summary of each new addition is listed below, but please review the complete document hosted on DCS for further details. [Ducati - Bulletins](#)

Revision 2 New Additions		
#	Subject	Model Affected
1	Front fork active leg position sensor cable	MULTISTRADA
2	Rear shock absorber	MULTISTRADA
3	Possible mismatch between fuel level indication and remaining range indication	MULTISTRADA
4	Possible pitting of exhaust manifold heat guard retaining screw surface treatment	HYPERMOTARD
5	Possible cosmetic defect on the headlight	SCRAMBLER
6	PDI operations	ALL MODELS
7	Scheduled maintenance check list update	ALL MODELS

This bulletin is only applicable for Ducati Motorcycles manufactured and configured for the Ducati North American market (USA, Canada and MX).

For questions about this Service Bulletin,
please contact your Service Area Manager.