

Subject

22-24MY Tundra and Tundra HV, V35A Engine, Oil Leak from Oil Filter Sealing Surface

Market

USA

Service Category

Engine/Hybrid System

Section

Lubrication

Applicability


2022-2024 MY Tundra and Tundra HV

APPLICABLE VEHICLES

2022-2024	Tundra	2022-2024	Tundra HV
-----------	--------	-----------	-----------

CONDITION

Vehicle may exhibit an oil leak from the sealing surface between the Oil Filter (PN: 9091510010) and the Oil Cooler (PN: 15710-F4010) in cold weather with sub-freezing temperatures.



RECOMMENDATIONS

If a vehicle is experiencing an oil leak anywhere around the Oil Filter gasket, please do the following:

1. Take clear pictures of the origin of the leak.
2. Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references