

QUARANTINE N873

QUARANTINE N873 – POWERTRAIN CONTROL MODULE SOFTWARE ERROR	
AFFECTED MODELS	24MY Range Rover and Range Rover Sport 4.4L V8 Models ONLY
VOLUME AFFECTED	US 1117 CAN 94
REPAIR	A concern has been identified where the Powertrain Control Module (PCM) software contains unexpected loss of functionality. This prevents certain regulatory mandated for Mode 6 test results from being stored and available for reporting in a handheld scan tool. As a result, the affected vehicles do not conform to the certified condition. A software update to the PCM will be required.
REPAIR TIME	0.2 hrs. + DIDO
CAMPAIGN LAUNCH	Quarantine notice issued on February 28th, 2024. Software release is targeted for March 2024.
NOTES	Please refer to the warranty portal to identify affected vehicles which must not be sold or delivered until the repair can be completed. 54 affected units in retailer inventory, 44 USA and 10 Canada.