

UPS N883- POWERTRAIN CONTROL MODULE SOFTWARE ERROR

UPDATE PRIOR TO SALE N883 – POWERTRAIN CONTROL MODULE SOFTWARE ERROR	
AFFECTED MODELS	24MY Range Rover and Range Rover Sport 3.0L 6-cylinder Models ONLY
VOLUME AFFECTED	US 184 CAN 7
REPAIR	A concern has been identified where the Powertrain Control Module (PCM) software contains unexpected loss of functionality. This prevents certain regulatory mandated for Mode 6 test results from being stored and available for reporting in a handheld scan tool. As a result, the affected vehicles do not conform to the certified condition. A software update to the PCM will be required.
REPAIR TIME	0.2 hrs. + DIDO
CAMPAIGN LAUNCH	Repair Launched on March 6th, 2024
NOTES	Please refer to BBSS for any vehicle in retailer inventory which must not be sold or delivered until the repair can be completed. As of March 19th, there are 32 affected units in USA retailer inventory.