

UPS CAMPAIGN N873- POWERTRAIN CONTROL MODULE SOFTWARE ERROR

UPS N873 – POWERTRAIN CONTROL MODULE SOFTWARE ERROR	
AFFECTED MODELS	24MY Range Rover and Range Rover Sport 4.4L V8 Models ONLY
VOLUME AFFECTED	US 933 CAN 87
REPAIR	A concern has been identified where the Powertrain Control Module (PCM) software contains unexpected loss of functionality. This prevents certain regulatory mandated for Mode 6 test results from being stored and available for reporting in a handheld scan tool. As a result, the affected vehicles do not conform to the certified condition. A software update to the PCM will be required.
REPAIR TIME	0.2 hrs. + DIDO
CAMPAIGN LAUNCH	Quarantine notice issued on February 28th, 2024. Repair launched March 21 st , 2024.
NOTES	Please refer to BBSS to identify affected vehicles in retailer inventory which must not be sold or delivered until the repair is completed. As of March 21st, there are 39 US and 10 Canadian affected units in retailer inventory, all Range Rover, most of the affected vehicles are being updated in port.