

CREAKING NOISE FROM GLASS ROOF PANEL

Customer Voice:

- A creaking type noise from the roof area is heard while driving.

Technical Description:

- This may be caused by interaction between the roof panel flip seal and the vehicle body.

Status:

- TSB JLRTB02079 has been updated to include Range Rover (L460) and Range Rover Sport (L461) model variants.
- Should a customer express a concern, please refer to the TSB for repair guidance.

Range Rover

- 22–24MY Range Rover (L460)
- 23–24MY RR Sport
- 20–24MY RR Evoque

Discovery

- 17-24MY Discovery
- ### Jaguar
- 18-24MY E-PACE

