

SRS SYSTEM FAULTS DUE TO AFTERMARKET DONGLES FITTED

Customer Voice:

- A Customer may complain of an SRS system warning message being displayed on the instrument panel.

Technical Description:

- This may be caused by aftermarket dongles being installed in the Diagnostic Link Connector (DLC).

Status:

- Many different aftermarket electronic devices found installed into the DLC have set spurious faults in the SRS module.
- When diagnosing a customer concern, please check for non approved aftermarket electronic devices installed into the vehicle electrical system.
- If not present at the time of diagnostic work being performed, ask the customer if such devices are used.

Range Rover

- 18-24MY Range Rover
- 18-24MY RR Sport
- 18-24MY RR Evoque
- 18-24MY RR Velar

Defender

- 20-24MY Defender

Discovery

- 18-24MY Discovery
- 18-24MY Discovery Sport

Jaguar

- 19-24MY E-PACE
- 18-24MY F-PACE
- 18-24MY F-TYPE
- 18-24MY XF

