



Service Bulletin


Bulletin No.: 24-NA-067

Date: April, 2024

INFORMATION

Subject: Headlamp Aim Is Uneven

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XT4	2024	2024	-	-	All	All

Involved Region or Country	North America, Europe, Middle East, Israel
Condition	 <p style="text-align: right; font-size: small;">6600469</p>
Cause	The notch pattern is normal and by design.
Correction	DO NOT replace the headlamps or adjust headlamp aim for this condition. This is a normal function of the lamps.

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Please communicate to the customer that the headlamp system is functioning as designed and this is a normal condition of their vehicle. Please share this information with the customer, including a copy of this message.

Parts Information

No parts are required for this repair.

Version	1
Modified	Released April 05, 2024

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION