



## **SSM 52428 2018-2024 Mustang - Ting/Pop/Clunk/Click Noise From Rear When Accelerating Or Applying Brakes - Built On 04-Dec-2017 And Through 01-Oct-2023**

Some 2018-2024 Mustang vehicles built on 04-Dec-2017 and through 01-Oct-2023 may exhibit a ting, pop, clunk, or click noise from the rear wheel hub when accelerating, applying brakes, or when shifting between drive/reverse (torque reversals). This condition may be caused by stick/slip between the hub and halfshaft interface during the torque reversals creating the ting, pop, clunk, or click noise. To correct the condition, refer to the Workshop Manual (WSM) to replace the halfshaft and hub assembly of the suspected side.